

 National Transportation Safety Board FOREIGN NOTIFICATION AVIATION		NTSB ID: ENG12RA034		Most Critical Injury: Fatal	
		Occurrence Date: 08/30/2012		Investigated By: Foreign	
		Occurrence Type: Accident			
Location/Time					
Nearest City/Place Taipei, Taiwan R.O.C.		State	Zip Code	Local Time 0143	Time Zone UTC
Aircraft Information					
Registration Number B-68801		Aircraft Manufacturer BRITTEN NORMAN		Model/Series Number BN2B/26	
Type of Aircraft: Airplane			Amateur Built Aircraft? No		
Injury Summary:		Fatal 3	Serious	Minor	None
Revenue Sightseeing Flight:			Air Medical Transport Flight:		
Narrative					
<p>Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:</p> <p>*** Note: The foreign authority was the source of this information. ***</p> <p>On August 30, 2012, a Britten-Norman BN-2B-26 Islander plane, registration number B-68801, powered by two Lycoming O-540-E4C5 reciprocating engines crashed in a high mountain area in northern Taiwan Republic of China while performing an aerial photography mission. The airplane was substantially damaged and all three persons on board were killed.</p> <p>The Aviation Safety Council of Taiwan, Republic of China, is investigating the accident. As the state of manufacture of the engines, the NTSB has designated a U.S. Accredited Representative under the provisions of Annex 13 to the Convention on Civil Aviation to assist the Taiwanese Authorities in their investigation.</p> <p>All inquiries concerning this accident should be directed to the Aviation Safety Council of Taiwan at:</p> <p>Aviation Safety Council 11 Floor, No. 200, Sec.3, Beixin Rd., Xindian City, New Taipei County 231, Taiwan, Republic of China Website: URL:www.asc.gov.tw</p> <p>Phone: 886-935628217 or 886-289127388 Updated on Sep 24 2012 3:33PM</p>					
FOREIGN INFORMATION - SUBJECT TO CHANGG					